


STATE OF INDIANA - COUNTY OF MONROE

SECTION 31, TOWNSHIP 7 N, RANGE 1 E

MONUMENT DESCRIPTION & REMARKS

SET 1/2" REBAR

RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 29 TH DAY OF DECEMBER, 19 86 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:
POLK

CORNER I.D.

E-23

TITLE


Index No. X-5
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)

T. 7 N R. 1 E 2nd P. Mer. N.F. Hoosier County Monroe State Indiana
1/4 section Corner common to sections _____, _____, _____, _____
_____ 31 and 32

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1814</u>	By <u>Arthus Henrie D.S.</u>	Year of search <u>1988</u>	By <u>R. Ratcliff</u>
Original monument <u>Post</u> (Wood post, stone, iron nail, pipe, etc.)		Monument found <u>None</u>	<u>R.L.S.#S0343</u>
Bearing Trees		Original Bearing Trees Found	
Species <u>B.Oak</u>	<u>R. Oak</u>	Species _____	_____
Diameter <u>10"</u>	<u>10"</u>	Diameter _____	<u>None</u>
Bearing <u>N48E</u>	<u>S27W</u>	Bearing _____	_____
Distance <u>8 lk</u>	<u>17 lk</u>	Distance _____	_____
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1860</u>	By <u>J.S. Buskirk MCS</u>	Year of search <u>1988</u>	By <u>Ron Ratcliff</u>
Where filed or recorded <u>Monroe Co. Surveyor</u>			<u>R.L.S.#S0343</u>
Monument <u>None called for</u> (Original, concrete post, iron rod, etc.)			<u>None</u>
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>R.Oak</u>	<u>R.Oak</u>	Species _____	_____
Diameter <u>8"</u>	<u>12"</u>	Diameter _____	<u>None</u>
Bearing <u>S23W</u>	<u>S35E</u>	Bearing _____	_____
Distance <u>33 lk</u>	<u>18 lk</u>	Distance _____	_____



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Rebar found at fence intersection fence lines
North, South and East and West.

At time of search:

1. Did you have the record description?
Yes X No _____2. How was search area located?
Pacing, chaining, photos, maps,
etc. Maps & Traverse3. Man hours spent in search 14. Do you think additional search might
recover evidence? Yes _____ No X5. Signature Ron Ratcliff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Bearing trees established by Ken Anderson R.L.S.Certified corner restoration certificate prepared: Yes _____ No X
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

Index No. 1-3
(Alphabetical - Numerical)


LAND CORNER RECORD (RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E Mer. N.F. Hoosier County Monroe State Ind
14 Section Corner common to sections 31, 32, and _____

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed _____		Year of search <u>1972</u>	By <u>H. Denton E.A.</u>
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found <u>No</u>	
Bearing Trees Species <u>B. Oak</u> <u>B. Oak</u> Diameter <u>10"</u> <u>10"</u> Bearing <u>N 48 E</u> <u>S 27 W</u> Distance <u>8 1/2</u> <u>17 1/2</u>		Original Bearing Trees Found Species _____ Diameter _____ Bearing <u>None</u> Distance _____	
Subsequent Corner Restoration Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ (Original, concrete post, iron rod, etc.)		Evidence of Subsequent Corner Restoration Found Year of search _____ By _____ _____ _____ _____	
Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____		Bearing Trees, Reference Objects _____ _____ _____ _____	



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

At time of search:

1. Did you have the record description?
Yes ☒ No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. photos, maps

3. Man hours spent in search 2 hrs

4. Do you think additional search might
recover evidence? Yes _____ No ☒

5. Signature H. Denton

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____